Goody Red Oxide Metal Primer

PRODUCT DESCRIPTION

Goody Red Oxide Primer is a economical General Purpose Metal Primer based on Synthetic Resin medium and Red Oxide of Iron as anti corrosive pigment. w duote

PERFORMANCE FEATURES & BENEFITS

- Very good adhesion to the surface
- Air drying cum stoving type.

RECOMMENDED USAGE

Goody Nerolac Red Oxide Primer is a General Purpose Primer for application on Iron and Steel surfaces.

SURFACE PREPARATION

Ensure the surface is clean, dry free from all mill scales, rust, defective or poorly adhering material, dirt, grease, wax etc. Remove all mill scales, rust, loose or poorly adhering materials by rubbing down using suitable abrasive paper and thereafter wipe off. Apply a coat of Goody Red Oxide Metal Primer before application of required top coats.



RECOMMENDED SYSTEM FOR APPLICATION

- Sand the surface with Emery Paper and wipe clean before application of subsequent coats.
- *Goody Red Oxide Metal Primer
- Nerolac Grey Knifing Paste Filler Air Drying Cum Stoving:- Pl. see NGKPF product data sheet for more details
- Air dry min 8 hrs for dry scuff & min 16 18 hrs for wet scuff. In case of stoving give flash off 30 minutes. Stoving schedule is 30 minutes at 100°C
- Juct Data • # PI. look for the individual finishing system given in respective Product Data Sheet.

Coverage** surface by	On smooth non absorbant	
brush.	surface 130 - 150 sq.	
	ft/ltr/coat.	¥ _
Drying Time	Surface Dry: Max 1 hr.	
@27° ± 2°C & RH 60 ± 5%	Recoating: Min. 8	
	hrs. Stoving : 30 minutes at	
	120°C	
Gloss Levels/ Sheen levels	Matt.	
Thinning	Upto 30% by volume using	
	Nerolac Gereral Purpose	
	Thinner.	
Flash Point	Not below 30°C	
Stability of Thinned Paint	Use within 24 hrs.	
Shelf-Life:	3 months from date of	
	manufacture in original	
	tightly closed containers	
	away from direct sunlight	
	and excessive heat.	

TECHNICAL DATA

**Actual coverage may vary depending on method & condition of application, surface roughness.

PRECAUTIONS

- Refer MSDS for "Goody Red Oxide Metal Primer" for safety measures & precautions.
- Store in well ambient conditions, Ventilated locations & away from the source of ignition and fire.
- Keep away from children.
- In case of eye/skin contact wash with plenty of water.
- Inhalation / Injection will cause danger. In case move to fresh air & consult medical practitioners in both the cases.
- Do not apply when ambient temperature might drop to level below 10°C within 4 hrs of application.
- Avoid extra thinning for better results.
- Stir well paint before application.
- The container must be tightly closed when not in use. Stir well before use.
- Use safety equipments like rubber or polythene gloves, safety goggles / glasses & face mask.

PACK SIZES

20 ltrs..

SHADE RANGE

Red Oxide.

